

US EPA ARCHIVE DOCUMENT

1. Incident Name	2. Date Prepared	3. Time Prepared	UNIT LOG ICS 214	
Kalamazoo River/Enbridge Spill	12/14/2012	1810		
4. Unit Name/Designators	5. Unit Leader		6. Operational Period :	
Containment Branch Recovery Team 3 (CBR-3)	Name:	Dan Capone START/US EPA	From:	12/14/2012 0700
	Position:	Operations Section Chief	To:	12/14/2012 1700
7. Personnel Roster Assigned				
<u>Name</u>	ICS Position			
Dan Capone	Operations Section Chief			
Rex Johnson	Containment Branch Director			
Sean Kane	Field Team Lead/CBR-3			
8. Activity Log				
Activity Area	(MP 36.75 LDB & MP 37.75 LDB Morrow Lake Delta)	LAT	LAT	
		Various	Various	
		(DD.MMMM)	(DD.MMMM)	
<u>OIL OBSERVED</u>	EXTENT OF OIL IMPACTED AREA			
	DENSITY OF OIL /SHEEN			
Total Collection Points				
Total Boom Deployed				
Activity	<u>Weston/START CBR 3 Team Activity:</u> General oversight documentation (photo and written) of Enbridge bathymetric survey team # 1 led by Luke Hodges (Stantec). Enbridge field team began survey measurements within Delta 'A' MP 37.75 LDB (Islands A & B) and completed transects; MP 37.75B (25 survey points), MP37.75C (27 survey points), MP37.75D (17 survey points), MP 37.75E (18 survey points).			
Health and Safety Issues	None			
Comments	Bathymetric survey data collected on 12-13-12 within the 36.75 RDB operational area (Delta 'A') has yet to be determined if it will be utilized by Enbridge GIS division. Enbridge has determined that control point utilized for survey activities was not sufficient for proper 'plotting' and consensus is still to be determined whether post-processing of data can be achieved.			

Water flow velocity and surface water elevation measurements were obtained for every transect line.

Cylindrical Sampling Device (CSD) #5 was temporarily removed prior to intrusive survey activities and replaced post survey activities.

Detailed field notes will be found in CBR-3 logbook.